



SISS Super Stain  
removes all stains from  
Synthetic and Stainless  
Steel Meshes



Always wear PPE  
(Personal Protective  
Equipment)



Stir SISS Super Stain  
prior to use



Apply SISS Super Stain  
to the screen using a  
spatula / palette knife  
or Squeegee



End result – Clean  
Fresh Mesh



Jet Wash the Screen



Leave to stand for 10  
minutes – remove as  
much SISS Stain  
Remover as possible



Ensure there is good  
coverage